Oil Field Environmental Incident Summary

Responsible Party: Trotter Construction **Well Operator:** XTO ENERGY INC. **Well Name:** CHARLSON 44-32H

Field Name: CHARLSON Well File #: 17162

Date Incident:8/25/2015Time Incident:1430Facility ID Number:County:MCKENZIETwp:154Rng:95Sec:32Qtr:

Location Description: South of wellpad

Submitted By: Kaylan Dirkx Received By:

Contact Person: Shawn Lee

P.O Box 206 12651 2nd St SW

Grassy Butte, ND 58634

General Land Use: Other - Described Above Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine

Other

Description of Other Released Contaminant:

no spill - grass fire.

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

None- fire was put out. No injuries, spill, or property damage. ACOE was notified via phone on 8/26/15. NDIC notified via phone on 8/26/15.

Areal Extent:

Approximately 1/2 acre south of the pad.

Potential Environmental Impacts:

None- fire was put out. No injuries, spill, or property damage. ACOE was notified via phone on 8/26/15. NDIC notified via phone on 8/26/15.

Action Taken or Planned:

Responsible party had a fire watch that night and will continue to have one on jobs.

Wastes Disposal Location: No waste

Agencies Involved:

Updates

Date: 8/27/2015 Status: Reviewed - Follow-up Required Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted areas south of the well pad. Followup is necessary to ensure proper cleanup.

Date: 9/17/2015 Status: Inspection Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

9/17/2015 at 14:39, on location. No visible impact off location; no further followup required.